IEEE Access
Multidisciplinary | Rapid Review | Open Access Journal

Received December 1, 2020, accepted December 12, 2020, date of publication December 21, 2020,
date of current version December 31, 2020.

Digital Object Identifier 10.1109/ACCESS.2020.3046100

Modeling and Assessment of Lightning Hazards to Humans in Heritage Monuments in India and Sri Lanka

VENKATESH SRINIVASAN[1], (Member, IEEE), MANJULA FERNANDO[2], (Senior Member, IEEE), SARATH KUMARA[2], (Senior Member, IEEE), THIRUMALINI SELVARAJ[3], AND VERNON COORAY[4], (Member, IEEE)

[1]School of Electrical Engineering, Vellore Institute of Technology, Vellore 632014, India
[2]Department of Electrical and Electronic Engineering, University of Peradeniya, Peradeniya 20400, Sri Lanka
[3]School of Civil Engineering, Vellore Institute of Technology, Vellore 632014, India
[4]Division for Electricity and Lightning Research, Department of Electrical Engineering, Uppsala University, 75236 Uppsala, Sweden

Corresponding author: Venkatesh Srinivasan (venkatesh.srinivasan@vit.ac.in)

This work was supported by the Department of Science and Technology (DST), Government of India, and the Ministry of Science, Technology and Research (MSTR), Government of Sri Lanka through the Bilateral India-Sri Lanka Research Project under Grant DST/INT/SL/P-14/2016/C&G.

ABSTRACT Lightning is one of the inevitable disastrous phenomena which in addition to damaging tall edifices, might also consequently endanger humans due to lightning-human interactions. This research focuses on analyzing lightning hazards to humans in the vicinity of heritage monuments in India and Sri Lanka. Five monuments which include three giant stupas namely Ruwanweliseya, Jethawanaramaya and Abayagiriya from Sri Lanka and two large temples namely Brihadishvara Temple and Gangaikonda Cholapuram from India have been chosen for investigation. Lightning-human interaction mechanisms namely direct strike, side flash, aborted upward leader, step and touch voltages have been investigated for the most onerous scenario on humans in the vicinity of the monuments. Firstly, the electro-geometric model as stipulated in standards has been implemented to ascertain the effectiveness of lightning protection to the structures. Subsequently, the study has been extended to the computation of step and touch voltages utilizing lightning current and electrostatic models based on Finite Element Method (FEM) using COMSOL Multi-physics®. Detailed plots of electric field and voltage distribution of lightning on humans due to a typical lightning current of 30 kA have been obtained. The final study involves assessment of current through humans which is estimated based on lumped R-C human model representation using OrCAD Cadence®. The analyses reveal that humans are invariably shielded against direct strikes whereas effects due to side flashes are minimal. During strikes to the monuments, high voltage may appear due to step and touch potential under dry conditions, though such effects could be mitigated by appropriate earthing system.

INDEX TERMS Lightning protection system (LPS), electro-geometric model (EGM), finite element method (FEM), rolling sphere method (RSM), lightning protection zone (LPZ).

I. INTRODUCTION

Lightning is a natural and inevitable phenomenon accompanied by significant transient current of high magnitudes which may consequently have severe deleterious effects on human, livestock whereby leading to fatal injuries, in addition to causing significant damages on tall human-made edifices and heritage monuments of importance. Among the two main types of lightning flashes, namely cloud-to-cloud (CC) and cloud-to-ground (CG), the CG lightning is the most severe hazard as far as human safety is concerned [1]. Such lightning strikes are formed by a group of cumulus clouds, which in turn propagate to the ground as a stepped leader and finally neutralize with the oppositely charged ground objects. Research studies indicate that almost two thirds of thunderstorms occurring in the globe are invariably in the tropical regions. From both the Indian and the Sri Lankan context though the geographical topology and weather undergo wide

The associate editor coordinating the review of this manuscript and approving it for publication was Giambattista Gruosso.

seasonal variations, a majority of the vast geography can be categorized as a part of tropical climate. Furthermore, recent studies indicate plausible connection between climate changes due to global warming and the need to have a clear understanding of the interactions between the frequency of occurrence and distribution of lightning discharges etc. It is also pertinent to note that studies based on recent research clearly indicate that the total number of fatal accidents to mankind caused by lightning around the world ranges from 6,000 to 24,000 per year [2], [3]. Considering recent lightning incidents, it is reported that annual deaths due to lightning strikes per million people in India and Sri Lanka are of the order of 2.5 during 21st century and it is comparatively higher than several other countries which have a non-tropical climate [4]. A study conducted on incidence of fatalities in India from 1979 to 2011 also indicated that a majority of incidents are reported in west and central part of India [4], [5]. Similarly, a study conducted on lightning incidents in 2003 in Sri Lanka reveals that the rate of lightning incidence is similar throughout the country and a majority of casualties has occurred due to step voltage and side flashes mainly due to ignorance, staying outdoors and in partially covered shelters near buildings during lightning [6].

Incidentally, it is also worth mentioning that during the past decade, there has been a surge in the number of damages related to lightning strikes on heritage monuments. Preservation of cultural heritage monuments which are invariably tall (structures had been built in ancient times by emperors either to commemorate their victories or constructed as places for religious congregation and worship) has become a challenging task since they are vulnerable to pollution, environmental hazards (chemical effluents from industries), fatigue of structural materials etc. In this context, it is also essential to recognize that detailed studies carried out in [7], [8] summarize a few of the major lightning strikes that have been reported to have caused substantial damages and deformation of the heritage structures, more so on world heritage monuments of importance. On the other hand, in a similar vein, it becomes pertinent to ascertain the human fatalities associated with lightning strikes both globally as well as from the context of Indian and Sri Lankan perspective, since it is obvious that both countries share a rich tradition of a large number of heritage sites of worship related to various religious faiths. Hence, it becomes extremely appropriate and essential to assess the risk index related to the heritage structure as well as hazard to humans (tourists, devotees, pilgrims etc) in line with the requirements of IEC 62305 [9]. Notwithstanding, it is also important that from the context of Indian and Sri Lankan heritage monuments, places of worship and important structures that signify historical relevance from the 1st century AD have been receiving wide attention and attraction from tourists and pilgrims worldwide. It is evident that such tall monuments could have the possibility of both cloud and ground (CG) initiated lightning flashes. The probability of such lightning strikes may furthermore be enhanced due to the likelihood of severe monsoon (both south-western and north-eastern) since the southern peninsular region of India and Sri Lanka experience intensive lightning activity.

Hence, it is obvious that both in Sri Lanka and India lightning protection system (LPS), which is in compliance with the relevant standards of the country as well as in line with the requirements stipulated in IEC 62305 [9] and NFPA 780 [10] has been installed. However, several challenges related to the effectiveness of such LPS installations namely efficacy of the lightning zone of protection (LPZ) in the context of large heritage structures, limitations and complexities based on the existing LPS scheme related to very tall structures [11], [12], complications in ensuring effective implementation of risk assessment in heritage due to human hazards due to lightning etc present considerable challenges to researchers.

This research hence focuses on carrying out detailed studies and analysis based on the LPS that has been already installed in the monuments that are being managed by the archeological conservation and preservation fraternity (Archaeological Survey of India and Sri Lanka). The existing LPS invites the prospective lightning leader which in turn passes through the down conductors to the ground, whereby necessitating a thorough analysis on the human-lightning interaction due to the likelihood of devotees staying in the vicinity and premises of the heritage structure. In this regard, with the objectives of identifying human safety hazards and mitigation methods, five human-lightning interaction mechanisms have been taken up for analysis based on specifically identified monuments which are reported to have had instances of lightning strikes in recent times. In the initial phase of the study, the protective angle method (PAM) and rolling sphere method (RSM) as stipulated in IEC 62305 and NFPA780 have been implemented by considering the geometrical and electro-geometrical aspects of the test cases to identify the lightning protection zone (LPZ) and the regions of shielding effectiveness in locations where the devotees stay during worship. In the second phase of the research, finite element based approach has been utilized to ascertain the indirect effect of lightning on devotees by considering the grounding efficiency in addition to the efficacy of LPZ based electro-geometrical models. In order to assess the effect of lightning strikes on human obtained from the finite element studies, a lumped human model representation [13] related to the various case studies has been implemented to ascertain the impact of human-lightning interaction.

II. AN OVERVIEW OF LIGHTNING SRIKES ON HERITAGE MONUMENTS IN INDIA AND SRI LANKA

It is evident from the foregoing discussion that intense monsoon associated with the tropical climate, inherently tall historical structures and edifices of significance, prolonged environmental fatigue associated with ancient structures etc have significant role in lightning strikes of structures in both the countries. From the Indian context, considerable analysis of lightning strikes and its associated damages to heritage monuments have been carried out by researchers and scientists of Archeological Survey of India (ASI). The reports of

FIGURE 1. Brihadishvara Temple – Lightning Strike shattered the spire atop Rajarajan Tower (Gopuram) in 2010.

FIGURE 2. Brihadishvara Temple – Lightning strike chipped-off mortar in precincts adjacent to main tower (Sri Vimana) in 2011.

FIGURE 3. Brihadishvara Temple – Lightning strike damaged a sculpture in the top portion of the entrance tower (Keralanthagan gopruam) in 2018.

such studies [14]–[22] relate to a variety of temples, churches and mosques of importance, including those of the world heritage monuments under the aegis of United Nations Educational, Scientific and Cultural Organization (UNESCO). Similarly from the Sri Lankan viewpoint, to the best of the knowledge of the authors of this research, such documented reports on lightning incidences are not in vogue. However, a few articles and news reports have indicated instances of lightning in Mihinthale stupa in 2010 [23] and strikes on metallic shelter enclosing the Avukana Buddha statue [24]. Further, recent studies of lightning strikes based on LPS and the associated surge counters installed in Jethawanaramaya and Abayagiriya stupas have also indicated some significant lightning incidents. The details of the various monuments and instances of lightning strikes including damages sustained by the structures are indicated in Fig.1, Fig. 2, Fig. 3, Fig. 4, Fig. 5, Fig.6, Fig. 7 and Table 1.

III. CASE STUDIES OF HERITAGE MONUMENTS IN INDIA AND SRI LANKA FOR ANALYSIS OF LIGHTNING-HUMAN INTERACTION

Five heritage monuments which are in addition also important places of worship have been selected to analyze and ascertain the effects of human safety due to lightning. In Sri Lanka,

FIGURE 4. Lightning Damages (a) Rathneswar Mahadeshwar Temple and (b) Jagadambika Temple in 2016 and 2015 respectively.



FIGURE 5. Lightning Strikes in (a) Jameshwar and (b) Nilamdhab Temples respectively.

FIGURE 6. Damaged roof and gables due to lightning strikes in Se Cathedral and Basilica of Bom Churches at Goa during 2015 and 2016 respectively.

FIGURE 7. Lightning strikes in Mihinthalaya stupa and Avukana Lord Buddha Statue respectively in Sri Lanka during 2010 and 2017 respectively.

three giant stupas [25] namely Jethawanaramaya, Abayagiriya and Ruwanweliseya have been taken up for human-lightning interaction studies [26], [27]. The three stupas are

TABLE 1. Reported lightning strikes to temples, churches and mosques in India and stupas and statues in Sri Lanka.

Heritage monument	Location and year	Nature of Lightning Damage
Brihadishvara Temple- Rajarajan Tower (Gopuram)	Thanjavur, India, 2010	1. One of the five spires (called 'kalash') on 'Rajarajan Thiruvayil (gopuram)', which is the middle gopuram from the entrance of the Big Temple, had been damaged following a lightning strike during the heavy rain to the structures 2. In 2014, it was observed that cracks had developed in the beams leading to seepage of rain water with possibility to consequent structural instability
Brihadishvara Temple- Precincts of Main Tower (Sri Vimana)	Thanjavur, India, 2011	1. Lightning struck the adjoining precinct structure (called 'Mandapam') of the main tower (called 'Vimana'). No incidence of lightning striking the main Vimana. But, lightning struck the precincts of adjoin structure of the tower, leading to cracks on its surface 2. The roof of the adjoining mandapam had developed cracks.
Brihadishvara Temple- Keralanthagan Gopuram	Thanjavur, India, 2018	1. A portion on the top right side of the gopuram was shattered and some pieces were felled. 2. A portion of the structure known as 'Keerthimugam' (ornate sculpture) has been shattered and was damaged
Ratneshwar Mahadev Temple (Leaning Temple of Kashi)	Varansi, India, 2016	1. Damaged due to heavy lightning led to shattering of the spire which weighed nearly 50 kg, atop the temple tower 2. However, there were no reports of injuries to human during the incident.
Devi Jagadambika Temple - Khajuraho	Madhya Pradesh, India, 2015	1. Lightning hit the top part of temple inside the Western group of temples damaging it. 2. The top part of the temple's Kalash (called 'Beejpurak') weighing around 6 kg had fallen. 3. Lightning also hit a 17-year-old girl, which was reported to be fatal.
Jameshwar Temple	Bhubaneswar, India, 2016	1. Deep crack developed on the walls of temple wall and a chunk of its ornate exterior hung precariously.
Nilamdhab Temple	Khandapada – Odisha, India, 2016	2. A portion of the temple suffered significant damages. 3. The crown of the temple had developed crack and the flag on top of the shrine was blown away under the impact of the strike
Basilica of Bom	Goa, India, 2015	1. Lightning struck the structure and damaged a pillar and tiles on the roof. 2. Lightning struck a pillar, which broke and felled a shower of stones and associated structure.
Se Cathedral	Goa, India, 2014	1. Lightning destroyed one of the gables, while also damaging roof tiles at several places. 2. The false ceiling of one of the halls near the priests' residence had been partly damaged.
Mihinthalaya	Anurudhapura, Sri Lanka, 2010	1. Lightning struck the Basel terrace (Pesawa) of the Chaitya of the Mihintale Raja Maha Viharaya.
Lord Buddha Statue	Avukana, Sri Lanka,2017	1. Lightning struck on the metal enclosure (roof) used for overall protection of the statue.

the 3rd, 5th and 7th tallest ancient brick structures respectively and recently some of their heights have been lowered during renovation activities. LPS have been installed and the devotees utilize the open space on the floor for congregating and worshiping. Considering spiritual and religious practices, wearing shoes, hats etc is prohibited in these places consequently exposing the human body to be in direct contact with the ground and more specifically the wet floor during the rainy season which is usually accompanied by lightning strikes. The details the monuments are indicated in Fig. 8, Fig. 9 and Fig.10 and Table 2.

From the Indian context, two giant medieval Chola temple monuments namely Brihadeesvara (Big temple or Peruvudayar Koil) and Gangaikonda Cholapuram [28] have been chosen for detailed analysis since it is evinced from the discussions in Section II that these structures have experienced repeated lightning strikes and considerable damages

FIGURE 8. Snapshot of Jethawanaramaya Stupa in Anuradhapura.

FIGURE 9. Photograph of Abayagiriya Vihara.



FIGURE 10. Snapshot of Ruwanweliseya.

TABLE 2. Details of stupas in Sri Lanka for lightning studies.

Monument	Description	Location	Dimensions
Jethawanaramaya, King Mahasen (273-301 AD)	World 3rd tallest ancient brick structure, (original height - 122 meters)	80.4015E 8.3515N	Height -70.7 m Radius-53.05m Effective floor area -23,550 m^2
Abayagiriya-King Valagambahu, (89-77 BC)	World 5th tallest ancient brick structure (original height - 106.7 meters)	80.3931E 8.3709N	Height - 74.7m; Radius - 50.9 m; Effective floor area -29,800 m^2
Ruwanweliseya-King Dutugemunu (140 BC)	World 7th tallest ancient brick structure (original height - 92 meters)	80.3942E 8.3500N	Height 92.4 m; Radius 41.9 m; Effective floor area - 15,800 m^2

TABLE 3. Details of temples in India for lightning analysis.

Monument	Description	Location	Dimensions
Brihadeeswara (Big) Temple – Thanjavur, King Rajaraja Chola (1003 AD-1010 AD)	10th century UNESCO heritage site 66 m tall Main Tower (called 'Sri Vimana')	10°46′58″ N 79°07′54″ E	Height of Sri Vimana - 66m; Effective floor area of temple complex-28,800 m^2
Gangaikonda Cholapuram-Jayankondam, King Rajendra Chola I (1025 AD- 1035 AD)	10th century UNESCO heritage site 51.04 m tall Main Tower (called 'Sri Vimana')	11°12′33.5 ″N 79°26′45″ E	Height of Sri Vimana–51.04 m; Effective floor area of temple complex-20,123 m^2

FIGURE 11. Snapshot of Brihadishvara Temple in Thanjavur.

FIGURE 12. Photograph of Gangaikonda Cholapuram in Jayankondam.

have been reported during the past decade [29]. Nonetheless, the uniqueness of the Brihadesvara temple include features such as granite stone construction, pyramid structure of the tower (main gopuram called 'Sri Vimana'), single granite stone spire (called the 'kalash' or 'stupi') weighing eighty tons, non-casting of the shadow of the Sri Vimana's spire during the entire day, a single stone construction of the 'sacred bull' (called 'nandhi') etc. People worship both in the sanctum sanctorum and the open area of the precincts of the temple. Details of the location and features of the temples are summarized in Table 3 and depicted in Fig. 11 and Fig. 12.

IV. MECHANISMS OF LIGHTNING–HUMAN INTERACTION AND LIGHTNING HUMAN MODELING

When a human stands near a tall structure and specifically in the context of heritage monument, human-lightning interaction can be categorized into five major categories namely direct strikes, side flashes, touch potential, step voltage and 'unsuccessful aborted upward leader' called the 'fifth mechanism' [30]. Direct strikes and side flashes are likely to occur when the human stands in the vicinity of a tall structure. On the other hand, a high voltage may appear on the body of the human due to the influence of the touch potential and step voltage especially when a tall structure is protected by an LPS

(usually the air terminal commonly referred to as ''Franklin rod'') and when the human is nearby a lightning strike. In the fifth mechanism, another unique case of lightning strike wherein an aborted upward leader may start from the head of the human and may become unsuccessful due to striking of lightning to a nearby tall structure which in turn is most probably protected by LPS and grounded appropriately. Another unique mechanism that has been reported in recent studies, called the 'sixth mechanism' of lightning also includes 'electromagnetic blasting' due to lightning which relates to human injuries closer to the point of lightning strikes [31]. However, a few of the researchers of the lightning community have reported their disagreement to this aspect and attribute the event more to the lightning primary injury [32].

Hence, considering the aforesaid lightning mechanisms, the ultimate effect and cumulative impact of exposure of human to lightning might result into very severe injuries and sometimes leading to fatal consequences due to cardiac arrest [33]. Fig.13 shows the five lightning human interfering mechanisms namely 1. direct strike to the human from the CG flash; 2. side flash due to a direct strike to the monument; 3. touch voltage due to the current flow through the down conductor; 4. step voltage due to CG lightning flash to a nearby area and 5. unsuccessful upward abort leader due to CG flash connecting to a nearby point.



FIGURE 13. Lightning- human interaction mechanisms: Direct strike, side flash, touch potential, step voltage and aborted upward leader.

A. DIRECT STRIKES

During cloud to ground (CG) flash, the stepped leader propagates towards the ground up to the striking point [34]–[39] and the striking distance (R_s) [40] is related to the lightning current which can be represented as

$$R_s = 10I^{0.65} \tag{1}$$

The current 'I' is determined by the accumulated charge 'Q' in the cloud, wherein $Q = 0.06I$ is utilized during implementation. For a typical lightning current of 30 kA and with the most onerous case of lightning current of 200 kA, the striking distances are 91.2 m and 313 m respectively while the charges are computed to be 1.8 C and 12 C respectively. The lightning current probabilities are given by

$$P = \frac{1}{1 + \left(\frac{I}{31}\right)^{2.6}} \tag{2}$$

Accordingly the probabilities for 30 kA and 200 kA are respectively 52% and 0.8%. It can be ascertained on whether human standing on the floor is hit by direct lightning according to the rolling sphere method (RSM).

B. SIDE FLASHES

When a monument is under the influence of direct lightning and lightning current flows through the monument (probably along the wet surface), an instantaneous voltage can be built up along path of the current. If a human stays in the vicinity of such a current-path, side flashes can occur from the point of the lightning path to the human. The prospective vulnerable locations of such lightning strike points can be obtained based on the RSM based layout that indicate the profile of the LPZ. Hence, it is evident that by injecting a standard lightning current with a wave-shape 10/350 μs to the striking point and allowing to flow through the surface, the potential distribution along the current path can be computed.

C. TOUCH POTENTIAL

When the LPS installed on the stupa is struck by lightning, current will flow through the down conductor and a corresponding voltage would be built up at the point of contact (usually at 1.5m from the ground). If the impedance of down conductor (Z_{DC}) is represented by the series connection of down conductor resistance and inductance together with earth resistance (R_E) representing the buried earth electrode, the voltage at the touch point can be computed as

$$V(t) = I(t)\,[Z_{DC} + R_E] \tag{3}$$

where $I(t)$ is an 10/350 μs lightning current wave shape as stipulated in line with IEC 60060.

By considering the human RC model representation during lightning, the current through the human body can be calculated from

$$I_{BODY}(t) = \frac{V(t)}{Z_H + R_A + R_B + \frac{(R_L + Z_F)}{2} + R_{Con}} \tag{4}$$

where R_{Con} is the contact resistance between the foot and the actual ground considered as zero potential which includes the resistance of the soil.

D. STEP VOLTAGE

When lightning current flows to the ground, the ground potential at the striking point rises instantaneously and decays along the surface of the flow. Hence, a voltage drop (ΔV) is induced across the legs of the human. Thus, the current

flowing through the body can be written as

$$I_{BODY}(t) = \frac{V(t)}{2(Z_F + R_L)} \tag{5}$$

E. ABORTED UPWARD LEADER

During leader propagation, charge accumulates at different points on the human body, including the head and the built-up voltage on the head of the human is in turn taken to be '$V(t)$'. The current through the body can be computed as

$$I_{BODY}(t) = \frac{V(t)}{Z_{HD} + R_N + R_B + \frac{(R_L + Z_F)}{2} + R_{Con}} \tag{6}$$

In order to compute and analyze the extent of influence of lightning parameters [25]–[29], the human lumped circuit model representation as indicated in Fig. 14 coupled with an impulse generator circuit representing induced voltage is proposed for implementation and simulation of the various lightning human mechanisms so as to obtain and compare the current through the human body for each of the lightning instances.



FIGURE 14. Lightning equivalent model representation of human.

The description of human model parameters taken up during the course of this research is summarized in Table 4. An impulse voltage generator which simulates the standard lightning impulse wave-shape has been modeled in OrCAD Cadence® software with typical values of the wave-shaping components namely R_1, R_2, C_1 and C_2 which are computed to be 200 Ω, 3200 Ω, 20000 pF and 1200 pF respectively.

V. IMPLEMENTATION OF FINITE ELEMENT ANALYSIS AND HUMAN MODELING FOR LIGHTNING STRIKE ASSESSMENT STUDIES

As a first step, 3-dimensional computer aided design (3-D CAD) layout drawings have been generated in AutoCAD® for the five selected monuments (three stupas from Sri Lanka and two temples from India) with their appropriate dimensions. The layout description also includes a sketch of the LPS which in turn comprises the air terminations, down conductor and grounding systems which are appropriately marked at the respective places of the monuments. In order to investigate possible lightning-human interaction (in this case, the prospective devotees), RSM based

TABLE 4. Description of human RC equivalent model representation during lightning strike.

Description	Impedance	RC Component	RC Values
Head	Z_{HD}	$R_{HD}//C_{HD}$	R_{HD}= 10 kΩ, C_{HD}= 10 μF
Neck	Z_N	R_N	R_N= 200Ω
Body	Z_B	R_B	R_B= 300 Ω
Arm	Z_A	R_A	R_H= 200 Ω
Hand	Z_H	$R_H//C_H$	R_H= 10 kΩ, C_H= 0.25μF
Leg	Z_L	R_L	R_L= 300 Ω
Foot	Z_F	$R_F//C_F$	R_F= 10 kΩ, C_F= 0.25 μF

EGM [41]–[43] has been implemented in line with stipulations laid out by IEC 62305 in order to identify the possible vulnerable lightning striking points on the monument including the space (floor) related to the location wherein the devotees usually congregate to offer prayers. In this research, a typical lightning current of 30 kA as well as the most onerous case of 200 kA lightning current have been considered in order to assess the entire lightning current spectrum related to human interaction studies.

Juxtaposing, a finite element method (FEM) based approach has been utilized to analyze and investigate the risk of lightning strike on human devotees by considering the effect of the propagating downward leader, in addition to ascertaining the role of the material properties of the selected object (monument). As a part of FEM based studies, 3-D model representation of the heritage monument have been conceived, generated and simulated in COMSOL Multiphysics® software. Since several research studies have indicated that lightning usually initiates from the cloud at about 2000 m from the ground, the model representation for simulation has been implemented based on an overall cylindrical configuration having a height of 2000 m with a radius of 1000 m. The flat surfaces of the cylinder have been assumed to be the cloud and the ground so as to assign Dirichlet boundary condition (fixed potentials) to these surfaces. On the other hand the curved cylindrical surface has been assigned as the Neumann boundary condition. In order to ensure meaningful simulation of the proposed structures, the monument is located (stupa is typically about 100 m tall while the temple towers called 'gopurams' are relatively less taller) at the center of the cylinder towards the ground (flat surface), so as to ensure symmetry of the geometry in addition to obtaining axisymmetric electric field profile. The downward leader has been placed from the cloud propagating towards the ground in steps of 50 m with uniformly distributed charges (1.8 C and 12 C respectively for lightning currents of 30 kA and 200 kA) placed on the leader. Since the typical thickness of the lightning channel is of the order of few centimeters while the size of the leader

propagation of selected model has been assumed to be in the range of 1000 m, it has been observed during the simulation studies that this aspect presented considerable challenges in introducing precise meshing (solution of partial differential equations of the finite elements) towards obtain accuracy of the order of centimeters. Hence, fine meshing has been implemented only to specific locations of importance (leader tip and possible touching surfaces) related the monument whereas coarse meshing has been applied on the other places of lesser significance.

It is pertinent to note that the five lightning interaction methods deliberated thus far are analyzed either as pre-lightning scenario (electrostatic model) or as post-lightning (current model). Accordingly, direct strike and aborted upward leader cases have been analyzed using the electrostatic model while the other three methods have been examined using the current model. Equations for the electrostatics and current model are indicated in (7) and (8).

$$\nabla \cdot D = 0 \tag{7}$$

$$\nabla \cdot J = \nabla . \left(-\sigma \nabla V - \frac{\partial \left(\varepsilon_0 \varepsilon_r \nabla V \right)}{\partial t} \right) \tag{8}$$

where D is electric flux density; J is current density; V is electric potential. Table 5 shows permittivity and electrical conductivity of materials used in the models.

TABLE 5. Details of material properties of heritage monuments.

Location	Material	Relative Permittivity	Conductivity (S/m) (dry, wet)
Stupa Structure	Brick, Stupa	4.2	0.001, 0.01
	Soil	9	0.001, 0.1
	Crushed rock foundation	6	0.0001
Temple	Granite gopuram	6	0.0001,0.001
	Soil	12	0.003, 0.04
	Crushed rock foundation	6	0.0001
LPS Surrounding Area	Copper Rod	1	5.8×10^{7}
	Air	1	8×10^{-15}

Each monument has been tested with each interaction method. The procedure used for the various interaction methods is summarized in Table 6.

Fig. 15 and Fig. 16 depict the generic formulation of the 3-D representation of a stupa taken up for FEM based studies.

Fig. 17, Fig. 18, Fig. 19, Fig. 20 and Fig. 21 depict typical snapshots of the FEM meshing carried out based on the implementation of the boundary conditions for the stupas and temples considered as a part of the research study which has been discussed in this section..

TABLE 6. Summary of procedure adapted for the analysis.

Interaction Type	Locations and Dimensions	Method
Direct strike (30 kA & 200kA)	The pilgrims are possibly at the furthermost point from the monument (minimum shielding)	• Implementation of RSM for checking the possibility of direct strike
Side flash (30 kA)	Probability of vicinity of devotees being closer to the path of the lightning current in the monument	• Deployment of FEM for ascertaining strikes at prospective points • Simulation of current flow along the surface
Step voltage (30 kA)	Installation of 3m long copper rods (at ground level and 0.3m below the ground level) placed 2m away from the monument in a 6m crushed rock foundation	• Implementation of FEM for obtaining the potential across the legs • Human model circuit representation for obtaining the current
Touch voltage (30 kA)	Installation of 3m long copper rods (at ground level and 0.3m below the ground level) placed 2m away from the monument in a 6m crushed rock foundation	• FEM for obtaining the touch voltage (at 1 m height of human) • Human model circuit representation for obtaining the transferred energy generator
Aborted upward leader (30 kA)	Pilgrims are possibly located at furthermost point from the monument (minimum shielding)	• FEM for obtaining the potential on the cranium of equivalent human model of devotee (at 1 m height of human) • Human model circuit representation for obtaining the current



FIGURE 15. Typical COMSOL layout for monument for analysis of lightning-human interaction mechanisms.

VI. RESULTS AND DISCUSSIONS

A. ANALYSIS OF IMPACT OF LIGHTNING ON HUMAN DUE TO DIRECT STRIKES

Fig. 22, Fig. 23, Fig. 24, Fig. 25 and Fig. 26 depict the loci of the leader tip and shielded area for a typical lightning current of 30 kA for the various stupas and temple monuments taken up for case studies of lightning protection zoning (LPZ). The onerous condition i.e. when the human is standing at the furthermost point on floor has been analyzed to ascertain the risk



FIGURE 16. Typical overall FEM model of stupa (2 km height, 1 km radius).



FIGURE 17. Typical meshing diagram for Ruwanweliseya.



FIGURE 18. FEM meshing diagram for Jethawanaramaya.



FIGURE 19. Typical meshing diagram for Abayagiriya.

of direct lightning strikes. It is evident from the detailed studies and analysis of the simulation that Ruwaneweliseya stupa and Gangaikonda Cholapuram temple have no risk for devotees from direct strikes for 30 kA lightning current. However, it also evident that the boundary lines of the rolling sphere computed and generated for 30 kA passes through



FIGURE 20. FEM meshing diagram for Big Temple.



FIGURE 21. Meshing diagram for Gangikonda Cholapuram.



FIGURE 22. Simulation of loci of LPZ and vulnerable points of lightning strikes on human in Ruwanweliseya.

the body for the most critical location in Jethwanaramaya, Abayagiriya stupas as well as Brihadesvara temple. From the context of the area affected with respect to the overall floor of the monument, the risk of direct strikes to such places is very minimal. Thus it is obvious that the devotees are nearly shielded by the monument structure against direct lightning, though in the case of the big temple as depicted in Fig. 25, the devotees inside the nandhi mandapam may be vulnerable to strikes.

B. ANALYSIS OF IMPACT OF LIGHTNING ON HUMAN DUE TO SIDE FLASH

Detailed studies and analysis have been carried out on the stupas and temples including its precincts based on the layout of



FIGURE 23. Loci of LPZ and vulnerable points of human in Jethawanaramaya.



FIGURE 24. Loci of LPZ and vulnerable points of human in Abayagiriya.



FIGURE 25. Loci of LPZ and vulnerable points of human in Gangaikonda Cholapuram.



FIGURE 26. Loci of LPZ and vulnerable points of human in Big Temple.

the COMSOL® simulation. The boundary current source is implemented and the simulated plots of the electric field distribution along the wet surface, floor and cranium of human



FIGURE 27. Boundary current source and its location in stupas during simulation and analysis.



FIGURE 28. Electric field distribution during lightning strike on Ruwanweliseya.



FIGURE 29. Electric field distribution during strike on Gangaikonda Cholapuram.

have been obtained. Fig. 27 depicts the implementation of the boundary current source for lightning strikes on the dome of stupas and temple monuments.

Fig. 28 and Fig. 29 display the plot of electric field intensity of lightning from the position of the human to that of the point of impact of lightning at the dome of stupa and gopuram.

C. ANALYSIS AND COMPARISON OF IMPACT OF LIGHTNING ON HUMAN DUE TO STEP POTENTIAL

In order to estimate step voltages, electric potential distribution in the vicinity of the grounding rod during lightning discharge through the LPS has been computed by means of COMSOL simulation. The tested lightning current is 30 kA of a wave shape of 10/350 μs. Since the depth of the installed grounding rod from the floor is also important for the step voltage, two cases i.e. rod on the ground surface and rod 0.3 m below the ground surface are also considered. In addition to that dry and wet conditions are simulated by adjusting the conductivity of soil and brick according to Table 5. As a special case, a copper plate buried at a 3 m depth and connected to the grounding rod is also considered. Fig. 30 shows potential distribution along the ground level in the vicinity of the rod for few selected cases: (a) dry conditions with rod on ground level, (b) dry conditions with rod 0.3 m below ground level, (c) dry conditions with rod on ground level along with a plate and (d) wet conditions with rod on ground level. As expected, higher ground potential rise occurs near the earth rod for all the cases. Highest potential rise can be observed when the rod is at the ground level under dry conditions, i.e. case (a). Installation of the rod 0.3 m below the ground level reduces the maximum ground potential rise almost by 50%.



FIGURE 30. Potential distribution along the ground plane in the vicinity of the grounding rod: distance measured from the center of the stupa with earth rod located 45 m away from the center.

However, its effect is limited to the region near the rod. In case of a plate, significant reduction of the potential can be seen over a wide area surrounding the rod. The potential during wet condition is much lesser (<1% of case (a)) than under dry conditions. By considering these observations two worst cases: (a) and (b) have been selected for further analysis. Table 7 summarizes the estimated step voltages of the pilgrim (devotee) when standing near the monument for the two cases. Two distances between legs i.e. standard 1 m distance and typical 0.3 m distance are considered.

It is clear from the results that the estimated steps voltages in general are high. However, the lightning interaction happens only within a period of several micro-seconds.

TABLE 7. Step voltages for different monuments.

Monument	At ground surface		0.3 m below ground surface	
	At 1m (MV)	At 0.3m (MV)	At 1m (MV)	At 0.3m (MV)
Ruwanweliseya	30	18	10	4
Abayagiriya	30	19	7.5	2.5
Jethawanaramaya	29	18	7.5	2.5
Gangikonda Cholapuram	29	18	8	3
Big Temple	29	18	10	4

The estimated steps voltages for different monuments are in the similar range irrespectively of height or shape of the structure. It is also clear that the estimated step voltages for 0.3 m distance are lower than those at 1 m but the variation does not show any linear relationship. From the optimistic viewpoint, usually devotees usually walk on the floor (0.3 m gap) rather than running (1m gap). Interestingly, when the grounding rods are placed about 0.3 m below the ground the step voltages reduces. The results indicate the possibility of reducing the step voltage due to the placement of a ground rod at a certain distance below the ground surface.

D. ANALYSIS AND COMPARISON OF IMPACT OF LIGHTNING ON HUMAN DUE TO TOUCH POTENTIAL

Table 8 shows the estimated touch voltages for different monuments considering different locations of the grounding rod. The touch potentials considered are at a height of 1 m along the down conductor connected to the ground. Similar to the step voltages, touch voltage values are also high and are reduced when the rod is placed 0.3 m below the ground surface. However, it is obvious that the chances of touching

TABLE 8. Touch voltages for different monuments.

Monument	At the ground surface (MV)	0.3 m below the ground surface (MV)
Ruwanweliseya	51	28
Abayagiriya	47	20
Jethawanaramaya	46	23
Gangikonda Cholapuram	47	24
Big Temple	47	24

the down conductor during lightning (usually rainy time) are highly unlikely. Thus, probability of having lightning interactions from touch voltage is at a minimal level.

E. ANALYSIS OF IMPACT OF LIGHTNING ON HUMAN DUE TO ABORTED UPWARD LEADER

In the case of aborted upward leader, the most onerous condition is during the instance of devotee standing at the furthermost point from the monument. Table 9 and Fig. 31 shows the estimated electric field on the head (cranium) of the human when the downward leader propagates from the cloud towards the human. Accordingly, 93 m is the striking distance for a typical 30 kA current. The estimation of the electric field beyond the striking point i.e. up to 45 m [30] is also included.

TABLE 9. Electric field distribution on the head of the human during leader Propagation.

Monument	Distance to the leader tip from ground (meters)			
Electric field [kV/m]	300	200	93	45
Ruwanweliseya	138	189	391	816
Abayagiriya	161	230	449	878
Jethawanaramaya	141	207	425	1052
Brihasesvara Temple	175	250	490	975
Gangikonda Cholapuram Temple	370	430	680	1175

Based on the results summarized in Table 9, it is evident that the estimated electric field at the head of the human increases with the leader propagation. However, it is observed that there are no significant differences among such variations for all the simulated cases. Detailed analysis during the simulation clearly confirms that the risk for the aborted upward leader is nearly same irrespective of the type of monument (stupa or temple). It is interesting to note that the estimated electric field at the head of the human is greater than 300 kV/m. Once the leader is neutralized with any possible upward leader which originates from the LPS installed on the stupa, the accumulated charge on the head of the human due to its electric field will pass through the human body on the surface or internally depending on the extent to which wetting occurs.

F. ANALYSIS OF LIGHTNING-HUMAN INTERACTION BASED ON HUMAN EQUIVALENT MODELING AND SIMULATION

Based on the details discussed in Section IV, an impulse generator to simulate lightning strokes has been implemented using OrCAD Cadence® in line with the stipulations laid out in IEC 62305 and as indicated in [13] with an impulse waveshape of 1.2 / 50 μs. The lightning impulse voltage obtained with appropriate values pertaining to each type of lightning



FIGURE 31. Enlarged snapshot view of electric potential and field distribution closer to the stupa for a 30 kA leader at 91.2 m from stupa top.

strike is in turn simulated in conjunction with the R-C equivalent human model representation as depicted in Fig. 14 and in [13] to ascertain the level of risk to human [44], [45] due to various factors such as role of earthing on the step and touch potential, distance of location from the point of strike due to side flash, influence of electric potential on the magnitude of currents through the body etc.

Simulation studies and analysis related to direct lightning strikes on the cranium due to dry lightning strikes, though impractical in real-time has been carried out to ascertain the effectiveness of the model in addition to ensuring calibration of the implemented simulation setup with the model that has been studied in [13]. Fig.32 depicts the implementation of the simulation related to direct lightning strike on human in the vicinity of Ruwanweliseya, since the probability the lightning strike of the giant stupa may not be ruled out, though such direct lightning (dry) is invariably impractical.

It is evident from Fig. 33 that the output current waveform reiterates the fact that direct strikes (dry) on the human may be detrimental and fatal, though impractical. Further, though a substantial 5 kA peak current is reached the time for the entire current to decay is of the order of 100 μs.

In order to ascertain the development of potential across the feet of a human separated by 1 m distance (as stipulated in standards) due to the lightning striking a nearby monument, equivalent R-C model representation studies have been carried out with varying distances of strikes at a distance of 1.5 m, 10 m and 20 m. Fig. 34 depicts the modeling and implementation of human lightning equivalent circuit due to



FIGURE 32. Simulation circuit for direct lightning strike on human in the vicinity of Ruwanweliseya.



FIGURE 33. Body voltage and body current waveforms for direct lightning strike on human.



FIGURE 34. Simulation of human step potential due to direct strike to the LPS of the monuments (with 5 Ω earthing resistance).

varying distances of strike and its influence on increase of current that is detrimental to human. This aspect becomes significant since pilgrims visiting important monuments tend to congregate and in a few cases, rest nearby the shadow of such tall heritage structures thereby necessitating the analysis of step and touch potential.

Based on the lightning simulation studies conducted for varying distances of 20 m, 10 m and 1.5 m from the point of lightning strike on the monument and human, it is evident that greater the distance from the point of lightning strike on monument (10 m to 20 m) the lower is the potential across the feet. Hence, the current flowing through the human body is not substantially large to have a detrimental effect. For a distance of 10 m from the structure the magnitude of peak current for 1 Ω and 5 Ω earthing system is of the order of 11 mA and 52 mA for a very short duration of about 1.5 μs. However, it is worth mentioning that for the distance within 1.5 m it is evident that substantial potential could develop across the feet leading to dangerous currents through human if the earth resistance cannot be maintained to a lower value. In this case it is observed that for earthing resistance system of 1 Ω and 5 Ω, peak current of the order of about 2.6 mA to 525 mA flows through the feet for the duration of 1.5 μs. Since the estimated currents are small, possible damages to the human such as muscle contraction in the legs might occur instead of causing fatal accidents. Based on these considerations, it is evident that appropriate and effective earthing system becomes a prerequisite for human safety in the vicinity of monuments. At the same time it is worth to mention that maintaining a very low earth resistance such as 1 Ω is extremely difficult since the overall earth resistance is characterized by resistances of both the conductor and the soilDetailed simulation studies carried out for various cases are depicted in Fig. 35, Fig. 36, Fig. 37 and Fig. 38 which indicate the current through human for earthing resistances of 5 Ω and 1 Ω for distances of 10m and 1.5m from the location of lightning flash.

From the context of touch potential and its impact on human safety aspects and as evinced from the discussion in Section IV, pilgrims in the vicinity of the monuments struck by lightning are vulnerable to increase in the potential at the point of contact of the down conductors which forms a



FIGURE 35. Step voltage and leg current waveforms of lightning flash at a distance of 10m from the monument with 5 Ω earthing resistance.



FIGURE 36. Step voltage and leg current waveforms of lightning flash at a distance of 10m from the monument with 1 Ω earthing resistance.



FIGURE 37. Step voltage and leg current waveforms of lightning flash at a distance of 1.5m from the monument with 5 Ω earthing resistance.



FIGURE 38. Step voltage and leg current waveforms of lightning flash at a distance of 1.5m from the monument with 1 Ω earthing resistance.



FIGURE 39. Simulation of human touch potential and current due to direct strike to the LPS of the monuments (with 1 Ω earthing resistance).



FIGURE 40. Current waveforms of human touch potential due to lightning on monument with earthing resistance of 5 Ω.

part of the LPS system installed in the monuments. Hence, studies and analysis have also been carried out to ascertain the touch potential of human in the vicinity of monuments considering that the down conductors are earthed for two varying values of earthing resistance namely 5 Ω and 1 Ω. Fig. 39 depicts the typical implementation of the simulation circuit for assessment of touch potential of human.

It is evident from the studies that substantial increase in the flow of current through the outstretched arm of the human is likely notwithstanding the type of earthing, since the impedance offered by the arms in much lesser than that of the value of impedance of the cranium and the torso. Hence,



FIGURE 41. Current waveforms of human touch potential due to lightning on monument with earthing resistance of 1 Ω.

a large value of the peak current in the range of 280 A to 1.45 kA for 1 Ω and 5 Ω earthing system respectively is observed for the duration of 1.5 μs. Fig. 40 and Fig. 41 display the waveforms of the current due to touch potential through the human for two varying values of earthing namely 5 Ω and 1 Ω which reiterate the observations during the simulation.

VII. CONCLUSION

It is evident from the detailed analysis and from the context of lightning-human interactions that giant heritage monuments in India and Sri Lanka are prone to lightning strikes whereby necessitating thorough analysis to ensure appropriate protection of humans in the vicinity of vulnerable places. The monuments taken up for investigation as a part of this study have reported lightning damages and recorded lightning events for their respective LPS. The detailed analyses of the five case studies taken up in this research clearly indicate significant aspects of lightning- human interaction which are summarized:

1. It is evident from the study that humans are invariably protected in the premises of the investigated monuments from direct lightning flashes. This aspect could be ensured based on carefully devised shielding zone of protection based on systematic implementing the RSM as stipulated in IEC 62305 whereby clearly demonstrating the efficacy of LPS in mitigating direct lightning strikes on human. The shielding effectiveness of the LPS devised during the course of this research also validated the analysis previously carried out by the authors of this research [30] whereby reiterating the findings of this study.

2. Lightning side-flashes may occur when humans are either closer to the down conductor of the LPS pertaining to the monument or to the lightning current path when a lightning directly strikes either the LPS or other non-protected areas respectively. However, considering the latter as a more onerous case, the study has found that the estimated electric field strength is not significant enough to initiate possible side flashes between the current path and the human. Values of electric field strength at a distance of about 10 m from the human is of the order of 200-300 V/m and hence found to be considerably low from the viewpoint of impact to human fatality.

3. It is evident that the risk of transferring lightning current through the human by instantaneously touching the lightning current path is considerably high. In this context, touching of the down conductor system of the LPS during lightning can be considered as the most stringent condition. The effect of lightning interactions to human by touch potential which has been modeled using FEM based current model in the post-lightning scenario clearly indicates the role played by effectiveness of grounding system of LPS and its impact on mitigating lightning strikes on human. Furthermore, the severity of impact of lightning on human due to touch potential is made evident as the values of peak current is observed to be in the range of 280 A to 1.45 kA and decays in about 12 μs.

4. Risk of lightning-human interaction due to step voltage may also play a major role during lightning when a human stands in an open area near the LPS grounding system of the monument. The typical spacing between two legs of a human near the heritage monuments is comparatively lesser and more conductive than the prescribed spacing as stipulated in standards. Accordingly the estimated step voltages are typically lower. On the other hand, the step voltages are substantially lower in wetted floors and it can be further mitigated by burying earth rods at appropriate distance below the ground level. In this research, for the investigation carried out for the most onerous condition, (human standing closer to the earth rod buried to the top of the floor under dry condition) the possible energy transfer to the human can be significantly dangerous and fatal. This aspect is also observed during the simulation studies of human model wherein substantial current of the order of 525 mA to 2.6 A which decays at about 60 μs, clearly indicated the criticality of the role played by earthing system in mitigating impact of lightning on human.

5. The aborted upward leader which is considered as the fifth mechanism of lightning-human interaction can also be exhibit significant risk in some of the investigated cases when the human stands at the furthermost point from the monument with minimal shielding from the structure.

ACKNOWLEDGMENT

The authors would like to thank the Archaeological Survey of India (ASI), New Delhi, and the Department of Archeology, Sri Lanka, for according permission and approval to undertake lightning protection studies of heritage monuments and for their continued support in this research work.

REFERENCES

[1] V. Cooray, *An Introduction to Lightning*. Dordrecht, The Netherlands: Springer, 2015.
[2] R. D. Holle, "Annual rates of lightning fatalities by country," in *Proc. 20th Int. Lightning Detection Conf.*, Tucson, AZ, USA, 2008, pp. 1–14.
[3] I. Cardoso, O. Pinto, Jr., I. R. C. A. Pinto, and R. L. Holle, "A new approach to estimate the annual number of global lightning fatalities," in *Proc. 14th Int. Conf. Atmos. Electr.*, Rio de Janeiro, Brazil, 2011, pp. 1–4.

[4] *Accidental Deaths & Suicides in India*, National Crime Records Bureau, Ministry Home Affairs, Government India, Mahipalpur, India, 2015.

[5] O. Singh and J. Singh, "Lightning fatalities over India: 1979-2011," *Meteorological Appl.*, vol. 22, pp. 770–778, 2015.

[6] C. Gomes, M. Ahmed, F. Hussain, and K. R. Abeysinghe, "Lightning accidents and awareness in South Asia: Experience in Sri Lanka and Bangladesh," in *Proc. 28th Int. Conf. Lightning Protection (ILCP)*, Kamasawa, Japan, vol. 10, Sep. 2006, pp. 1240–1243, Paper VIII.

[7] S. Sreedhar and S. Venkatesh, "Lightning strokes and its effects on historical monuments, heritage properties and important landmarks a detailed perspective of traditional and scientific methods of lightning protection systems," *Int. J. Eng. Technol.*, vol. 7, no. 2, pp. 784–794, 2018.

[8] T. Selvaraj, V. Srinivasan, S. Raneri, M. Fernando, and S. Jayasingh, "Response of organic lime mortars to thermal and electrical shocks due to lightning strikes," *Sustainability*, vol. 12, no. 17, 7181, pp. 1–24, Sep. 2020.

[9] *Protection Against Lightning: IEC 62305-1 to 4*, Standard IEC 62305, 2020.

[10] *Standard for the Installation of Lightning Protection Systems*, Standard NFPA 780: National Fire Protection Association, 2017.

[11] C. Bouquegneau, "A critical view on the lightning protection international standard," *J. Electrostatics*, vol. 65, nos. 5–6, pp. 395–399, May 2007.

[12] T. Horváth, "Problems with application of the protection angle method at three-dimensional structures," in *Proc. 29th Int. Conf. Light. Prot. (ICLP)*, Uppsala, Sweden, Jun. 2008, pp. 4–5.

[13] V. Cooray, *The Lightning Flash*. Edison, NJ, USA: IET, 2014.

[14] (Nov. 28, 2010). *Kalasam on Big Temple's Rajarajan Thiruvayil damaged in Lightning Strike*. Accessed: Nov. 4, 2020. [Online]. Available: https://www.thehindu.com/news/national/tamil-nadu/Kalasam-on-Big-Temples-lsquoRajarajan-Thiruvayil-damaged-in-lightning-strike/article15719847.ece

[15] (Jun. 6, 2018). *Lightning Arrester Averts Major Damage to Big Temple Gopuram*. Accessed: Nov. 8, 2020. [Online]. Available: https://www.dtnext.in/News/TamilNadu/2018/06/06020148/1075055/Lightning-arrester-averts-major-damage-to-Big-Temple-.vpf

[16] (Mar. 13, 2016). *Varanasi: Part of 500-Year-Old Ratneshwar Mahadev Temple Collapses Due to Lightning*. Accessed: Nov. 11, 2020. [Online]. Available: https://www.dnaindia.com/india/report-varanasi-part-of-500-year-old-ratneshwar-mahadev-temple-collapses-due-to-lightning-2188737

[17] (Jun. 3, 2015). *Lightning Strikes Heritage Site in Khajuraho, Damages Temple*. Accessed: Nov. 11, 2020. [Online]. Available: https://www.hindustantimes.com/bhopal/lightning-strikes-heritage-site-in-khajuraho-damages-temple/story-cL4o6IwUsltvSRcytL20KM.html

[18] (Aug. 2, 2016). *Temple Bears Lightning Brunt—Chunks Falls of 11th Century Structure*. Accessed: Nov. 11, 2020. [Online]. Available: https://www.telegraphindia.com/odisha/temple-bears-lightning-brunt/cid/1507044

[19] (Oct. 12, 2014). *Lightning Strikes Se Cathedral*. Accessed: Nov. 12, 2020. [Online]. Available: https://www.heraldgoa.in/Goa/Lightning-strikes-Se-Cathedral/79621

[20] (Jun. 6, 2015). *Lightning Strike Damages Basilica Roof, Tiles, Façade*. Accessed: Nov. 11, 2020. [Online]. Available: https://timesofindia.indiatimes.com/city/goa/Lightning-strike-damages-Basilica-roof-tiles-faade/articleshow/47560945.cms

[21] (Sep. 24, 2016). *Centuries-Old Temple Damaged in Lightning Strike*. Accessed: Nov. 12, 2020. [Online]. Available: https://www.orissapost.com/centuries-old-temple-damaged-in-lightning-strike

[22] A. Bandara, C. Ratnayake, D. Ambepitiya, J. R. S. Kumara, M. A. R. M. Fernando, S. Venkatesh, and D. K. Jayaratne, "Lightning risk analyses on protected Sri Lankan heritage stupas," in *Proc. 13th IEEE Int. Conf. Ind. Inf. Syst. (ICIIS)*, IIT Ropar, India, 2018, pp. 322–327.

[23] (Apr. 25, 2010). *Lightning Strikes Basel Terrace of Mihintale Vihara Chaitya*. Accessed: Nov. 12, 2020. [Online]. Available: http://www.island.lk/2010/04/25/news4.html

[24] (Nov. 1, 2017). *Avukana Temple: Increased Lightning Due to Protective Covering*. Accessed: Nov. 12, 2020. [Online]. Available: http://www.adaderana.lk/news/43919/avukana-temple-increased-lightning-due-to-protective-covering

[25] P. M. Ranaweera, *Stupas of Sri Lanka—A Technological Study*. Colombo, Sri Lanka: S. Godage & Brothers Limited, 2018.

[26] U. K. R. M. H. Rajapaksha, J. R. S. S. Kumara, M. A. R. M. Fernando, K. A. S. Susantha, S. Venkatesh, and D. K. Jayaratne, "Possible lightning hazards to humans near giant ancient stupa," in *Proc. 14th Conf. Ind. Inf. Syst. (ICIIS)*, Kandy, Sri Lanka, Dec. 2019.

[27] A. Bandara, C. Ratnayake, D. Ambepitiya, J. R. S. S. Kumara, M. A. R. M. Fernando, K. A. S. Susantha, and D. K. Jayaratne, "Lightning analyses on ancient and new giant stupas," Inst. Eng., Sri Lanka Kandurata Chapter, Kandy, Sri Lanka, Tech. Rep. 1, 2018.

[28] S. R. Balasubrahmanyam, *Middle Chola Temples-Rajaraja I to Kulottunga I*. Haryana, India: Thomson Press, 1975.

[29] S. Venkatesh, S. Thirmalini, S. Chandrasekaran, S. Sreedhar, K. Kakria, M. A. R. M. Fernando, and J. R. S. S. Kumara, "Three-dimensional implementation of modified rolling sphere method for lightning protection of giant medieval Chola monument in South India," in *Proc. 14th IEEE Int. Conf. Ind. Inf. Syst. (ICIIS)*, Kandy, Sri Lanka, Dec. 2019, pp. 535–540.

[30] M. Becerra and V. Cooray, "On the interaction of lightning upward connecting positive leaders with humans," *IEEE Trans. Electromagn. Compat.*, vol. 51, no. 4, pp. 1001–1008, Nov. 2009.

[31] R. Blumenthal and N. J. West, "Investigating the risk of lightning's pressure blast wave," *South Afr. J. Sci.*, vol. 111, pp. 1–5, Apr. 2015.

[32] C. Gomes, "Lightning related human risks," *Environ. Risk Assessment Remediation*, vol. 1, no. 3, pp. 1–15, 2017.

[33] T. Christophides, S. Khan, M. Ahmad, H. Fayed, and R. Bogle, "Cardiac effects of lightning strikes," *Arrhythmia Electrophysiol. Rev*, vol. 6, no. 3, pp. 114–117, Aug. 2017.

[34] R. B. Anderson and A. J. Eriksson, "Lightning parameters for engineering applications," *Electra*, vol. 69, no. 69, pp. 65–102, Mar. 1980.

[35] K. Berger, R. B. Anderson, and H. Kroninger, "Parameters of lightning flashes," *Electra*, no. 41, pp. 23–37, Jul. 1975.

[36] "Guide to procedures for estimating the lightning performance of transmission lines," CIGRE, Paris, France, Tech. Rep. 63, Oct. 1991.

[37] R. B. Anderson and A. J. Eriksson, "A summary of lightning parameters for engineering applications," CIGRE, Paris, France, Tech. Rep. 1, 1980, pp. 1–12, Paper 33-06.

[38] L. Dellera *et al.*, "Lightning exposure of structures and interception efciency of air terminals," CIGRE 118, Paris, France, Tech. Rep. CIGRE TF 33.01.03, 1997.

[39] V. A. Rakov and A. M. Uman, "Some properties of negative cloud-to-ground lightning flashes versus stroke order," *J. Geophys. Res. Atmos.*, vol. 95, No. D5, pp. 5447–5453, 1990.

[40] V. Cooray, V. Rakov, and N. Theethayi, "The lightning striking distance-Revisited," *J. Electrostat.*, vol. 65, no. 5, pp. 296–306, 2007.

[41] M. Nassereddine and A. Hellany, "Designing a lightning protection system using the rolling sphere method," *Proc. Int. Conf. Comput. Electr. Eng. (ICCEE)*, vol. 1, 2009, pp. 502–506.

[42] B. Brusso, "The electrogeometrical model of the rolling sphere method [History]," *IEEE Ind. Appl. Mag.*, vol. 22, no. 2, pp. 7–70, Mar. 2016.

[43] Q. Xie, S. Baron, S. Fortin, and F. P. Dawalibi, "Rolling sphere method using 3D Graphics approach," in *Proc. IEEE Asia–Pacific Power Energy Eng. Conf. (APPEEC)*, Mar. 2009, pp. 1–4.

[44] V. Cooray, C. Cooray, and C. J. Andrews, "Lightning caused injuries in human," *J. Electrostat.*, vol. 65, no. 5, pp. 388–394, May 2007.

[45] C. J. Andrews, M. A. Cooper, M. Darveniza, and D. Mackerras, *Lightning Injuries: Electrical, Medical, and Legal Aspects*. Boca Raton, FL, USA: CRC Press, 1991.

VENKATESH SRINIVASAN (Member, IEEE) was born in Tamil Nadu, India, in 1973. He received the B.E. degree in electrical and electronics engineering from Annamalai University, India, in 1994, and the master's degree in technology-high voltage engineering and the Ph.D. degree in high voltage engineering from SASTRA University, in 2004 and 2013, respectively. He was with Alstom Limited, Systems Group-India, T&D Projects Division, as an Assistant Manager of Engineering and Quality Assurance, from 1999 to 2001. Then, he worked with the Department of Electrical and Electronics Engineering, School of Electrical and Electronics Engineering, SASTRA Deemed University, India, as a Senior Assistant Professor, from 2006 to 2015. He is currently working with the School of Electrical Engineering, Vellore Institute of Technology, Vellore, as an Associate Professor. His specific areas of interests include condition monitoring of electrical insulation systems, EHV transmission, lightning protection systems for structures, and computational intelligence. He is a member of IEEE Dielectric Insulation Society, IEEE Industrial Applications, and Smart Grid Community.

MANJULA FERNANDO (Senior Member, IEEE) was born in Colombo, Sri Lanka, in 1966. He received the B.Sc. (Eng.) degree from the University of Peradeniya, Sri Lanka, in 1993, the Tech. Lic. degree from the Royal Institute of Technology, Stockholm, Sweden, in 1997, and the Ph.D. degree from the Chalmers University of Technology, Gothenburg, Sweden, in 1999. He is currently a Senior Professor and the Head of the Department of Electrical and Electronic Engineering. His research interests include condition monitoring, alternative insulation, and outdoor insulation. He is a Chartered Engineer, an International Professional Engineer, and a Fellow of Institution of Engineers, Sri Lanka. He was the Founder Chair of IEEE Sri Lanka Power and Energy Society Chapter in 2010, the General Chair of 4th IEEE International Conference on Industrial and Information Systems, in 2009, and the IEEE-Chair of Sri Lanka Central Region Subsection in 2009/2010.

SARATH KUMARA (Senior Member, IEEE) was born in Ratnapura, Sri Lanka, in 1979. He received the B.Sc. (Eng.) (Hons.) degree in electrical and electronic engineering and the M.Phil. degree from the University of Peradeniya (UOP), Sri Lanka, in 2004 and 2007, respectively, and the Tec.Lic. and Ph.D. degrees from the Chalmers University of Technology, Gothenburg, Sweden, in 2009 and 2012, respectively. He is currently a Senior Lecturer with the Department of Electrical and Electronic Engineering, University of Peradeniya. His research interests include high voltage insulation materials, condition monitoring, gas discharge simulations, high voltage testing, and power system modeling. He is an Associate Member of IESL.

THIRUMALINI SELVARAJ was born in Tamil Nadu, India, in 1974. She received the B.E. degree in civil engineering from Madras University, in 2005, the M.E. degree in environmental engineering from Anna University, in 2007, and the Ph.D. degree from the Vellore Institute of Technology, India, in 2015, in the domain of heritage lime mortar characterization and simulation. Her primary areas of research include scientific methods for restoration and repair of heritage structures, characterization of traditional building material using analytical techniques, carbonation, and self-healing studies using organic lime mortars with emphasis on optimization of lime mortars products.

VERNON COORAY (Member, IEEE) received the Ph.D. degree in electricity with special attention to electrical transients and electrical discharges from Uppsala University, Sweden, in 1982. In 2000, he was promoted to the rank of Full Professor in Electricity with special attention to transients and electrical discharges with the Division for Electricity and Lightning Research, Uppsala University, where he was the Head of the Division for Electricity and Lightning Research, Department of Engineering Sciences, from 2000 to 2002. He has authored or coauthored more than 400 scientific articles and 22 book chapters on physics of lightning and electrical discharges, lightning interaction, and electromagnetic compatibility. He is an editor of three books, *The Lightning Flash* (IEE, 2003), *Lightning Protection* (IEE, 2009), and *Lightning Electromagnetics* (IEE, 2012). He is also the Vice President of the scientific committee of the International Conference on Lightning Protection (ICLP) and a member of the scientific committee of the Symposium on Lightning Protection (SIPDA). He is the Editor-in-Chief of the *Journal of Lightning Research*. He was also a guest editor of two issues of *Atmospheric Research* and two issues of the *Journal of Electrostatics*.